



Errata to Energy and Internal Volume of Refrigerating Appliances

AHAM HRF-1-2008

Correction Sheet
Issued November 17, 2009

Copyright © 2009 by the Association of Home Appliance Manufacturers, Inc. All rights reserved. Published 2009. Printed in the United States of America.

This correction sheet may be freely reproduced and distributed in order to maintain the utility and currency of the underlying Standard. This correction sheet may not be sold, licensed or otherwise distributed for any commercial purposes whatsoever. The content of this correction sheet may not be modified.



Leadership > Knowledge > Innovation

Correction Sheet to AHAM HRF-1-2008

Page i, Table of Contents, Clause 4 title, should read as follows:

METHOD FOR COMPUTING REFRIGERATED VOLUME OF REFRIGERATORS, REFRIGERATOR-FREEZERS,
WINE CHILLERS AND FREEZERS

Page 7, Section 4 heading, should read as follows:

METHOD FOR COMPUTING REFRIGERATED VOLUME OF REFRIGERATORS, REFRIGERATOR-FREEZERS,
WINE CHILLERS AND FREEZERS

Page 7, Clause 4.1, should read as follows:

This section describes methods for computing total volume (Section 3.30.3) of refrigerators,
refrigerator-freezers, wine chillers and freezers.